

## Carbide 3D Shapeoko Training

### Step 1.

Open the Flash train website and follow the log-in procedure using your Kent State username and password

<https://flashtrain.kent.edu/Public/login.aspx>

### Step 2.

Click the drop-down arrow for the “**Testing/Training/Tracking**” menu

Click the “**Select Test**” option

### Step 3.

Once you have accessed the “**SELECT A TEST TO TAKE**” page click the drop-down arrow for “**Select Test**”

Scroll the list to locate “**CAED FabLAB Shapeoko CNC Tutorial and Test**” and select

### Step 4.

Once you have accessed the correct test, you can review the training materials at the bottom of the page.

When ready click the “**Take selected test**” icon

Complete and pass the test and then proceed to the CAED / FabLAB to finish the training by preparing a file and milling on the CNC Shapeoko